

Exhaust Stack/Guard Rotation

- **Issue:** The Exhaust stack/guard assembly will rotate and the guard will hit the cab/sleeper.
- **Resolution:** Replace the existing wide-band clamp between the DPR/SCR outlet pipe and the exhaust stack with a different clamp.
- A50BFE clamp provides increased clamp load.



“Old” wide-band clamp



A50BFE clamp