


All Places > Tech Talk Forum > Discussions

8 Replies Latest reply: Nov 5, 2015 9:33 AM by Scott Trippel



Carlson Anderson Oct 29, 2015 10:01 PM

DD FUEL PUMPS

This question is **Not Answered**.

We had had Fourteen fuel pumps fail in the last month 45 days..
dd13 ,15 epa 07/10 .
Has anyone had the same problem.?

201 Views Tags:

Average User Rating

(0 ratings)

Your Rating:



Scott Trippel Oct 30, 2015 7:20 AM (in response to Carlson Anderson)

Re: DD FUEL PUMPS

You are talking about the low pressure or high pressure side?

We have had only a few where the high pressure side cannot make rail pressure match desired.

Actions

Like (0)



Carlson Anderson Oct 30, 2015 9:16 AM (in response to Scott Trippel)

Re: DD FUEL PUMPS

high side, wiping out the cam shafts and rollers , filling the fuel tanks full of metal.

Actions

Like (0)



Scott Trippel Oct 30, 2015 11:43 AM (in response to Carlson Anderson)

Re: DD FUEL PUMPS



Wow, I have heard of that in the EPA 07 DD before but have not had that happen here.

Actions

Like (0)



Kyle Siebert Oct 30, 2015 6:00 PM (in response to Carlson Anderson)

Re: DD FUEL PUMPS

Ive heard of biofuel doing this to high pressure fuel pumps.

Actions

Like (0)



Daniel Mitchell Nov 4, 2015 6:03 AM (in response to Carlson Anderson)

Re: DD FUEL PUMPS

More than likely a fuel quality issue if I were to guess. I would definitely get a fuel sample without metal and have it tested...

Actions

Like (0)



Tyler Robertson Nov 4, 2015 10:29 AM (in response to Carlson Anderson)

Re: DD FUEL PUMPS

I agree it is likely a fuel issue. Is it all local customers or from all over? Is it a fleet of trucks from the same company? might be an issue right at the pump if it is the case.

Actions

Like (1)



Jason Tearman Nov 5, 2015 8:21 AM (in response to Tyler Robertson)

Re: DD FUEL PUMPS

Detroit issued a map of fuel locations after Shreveport area and southern states had a rash of dd15 fuel pumps. Our location alone was replacing 3-5 a week, full fuel system jobs for most of 2013 and 2014. Due to Bio diesel causing roller failure in the high pressure pumps.

Actions

Like (0)

Scott Trippel Nov 5, 2015 9:33 AM (in response to Jason Tearman)



Re: DD FUEL PUMPS

Wow, what was the problem? Too much Bio?

Here in Alberta it is mandatory that summer fuel has 10% Bio. In the winter 0% and when they blend in September it is still 0% Bio.

Actions

Like (0)