

Detailed Inspection Report as of 4/29/2022

CARRIER INFORMATION

TIME/LOCATION

Carrier [REDACTED]
 U.S. DOT# [REDACTED]
 Carrier Address [REDACTED]
 [REDACTED]

Report # [REDACTED]
 Report State: SC
 State: SC
 Date: 3/12/2022
 Start Time: 0845
 End Time: 0910
 Level: III. Driver-Only
 Facility: Roadside
 Post Crash Inspection: No
 Hazmat Placard Required: No

VEHICLE INFORMATION

UNIT	TYPE	MAKE	PLATE STATE	PLATE NUMBER	VIN
1	Truck Tractor	FRHT	IN	[REDACTED]	[REDACTED]
2	Semi-Trailer	TRLR	SC	[REDACTED]	[REDACTED]

CARRIER VIOLATIONS

VIO CODE	SECTION	UNIT	OOS	DESCRIPTION	INCLUDED IN SMS	BASIC	REASON NOT INCLUDED IN SMS
392.2-SLLS1	392.2	Driver	No	State/Local Laws - Speeding 1-5 Miles Per Hour Over The Speed Limit.	No		Not used in SMS Calculation